Suzanne Steab - May 2010 Inspection Reports

From:

Karl Houskeeper

To:

dshaver@coalsource.com

Date:

6/22/2010 8:25 AM

Subject:

May 2010 Inspection Reports

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments: Centennial May 2010.pdf; Crandall May 2010.pdf

Dave,

Attached is the May 2010 inspection reports for Centennial and Crandall Mines.

Thanks,

Karl



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERTL. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

|--|

OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0070019
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, May 11, 2010
Start Date/Time:	5/11/2010 8:00:00 AM
End Date/Time:	5/11/2010 1:00:00 PM
Last Inspection:	Wednesday, April 14, 2010

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast/Sleet, Temp. 30 Deg. F.

InspectionID Report Number: 2351

Reprocessing

Accepted by: jhelfric 5/17/2010

Permitee: ANDALEX RESOURCES INC TOWER DIVISION Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: CENTENNIAL MINE

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

8.83	Total Permitted
7.19	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

☐ Other

Types of Operations ✓ Federal ✓ Underground **✓** State ☐ Surface County Loadout ✓ Fee Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Date

Tuesday, May 11, 2010

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070019 Inspection Type: PARTIAL

Inspection Date: Tuesday, May 11, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

1.	Permite Change Transfer Denound Cal-	Evaluated	Not Applicable	Comment	Enforcement
_	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<u> </u>		<u> </u>	
3.	Topsoil				<u> </u>
4.a	Hydrologic Balance: Diversions	✓		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	V	✓		
6.	Disposal of Excess Spoil, Fills, Benches	V	V		
7.	Coal Mine Waste, Refuse Piles, Impoundments	<u> </u>	V		
8.	Noncoal Waste	~		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	П		П	

Permit Number: C0070019
Inspection Type: PARTIAL

Inspection Date: Tuesday, May 11, 2010

Page 3 of 3

2. Signs and Markers

The mine identification sign is in place at the point of public access to the permit area. The sign contains the required information.

4.a Hydrologic Balance: Diversions

The culvert outlet up canyon from the bath house is half full of sediment.. The outlet needs to be cleaned.

8. Noncoal Waste

A plastic jug is in the diversion looking up canyon on right side of main access road, adjacent to the lamp house. Large metal sheet in diversion looking up canyon on left side of main access road, below shop area. Both of these items should be collected and removed from the diversions. Items should be placed in the appropriate noncoal storage facility.